RUNYON SURFACE PREP
RENTAL & SUPPLY

RSP DIAMOND TOOLING GUIDE

SURFACE PREPARATION

METHOD	DRY		WET OR DRY	
	TRAC PCD		NITRO (MASTIC/GLUE REMOVAL)	
GRIT:	PCD	directional	16,30	
ATTACH:	Q8		Q8	

CONCRETE GRINDING

METHOD	WET OR DRY			
NAME:	QUATTROS	TURBO TULIP	RSP 8-SEG	RSP 10-SEG
GRIT:	16, 30, 70, 120	16, 30, 70, 120	16, 30, 70, 120	16, 30, 70, 120
BOND:	soft, medium, hard	medium	soft, medium, hard	soft, medium, hard
ATTACH:	Q8	Q8 or velcro back	Q8	Q8

TRANSITIONALS/HONING

METHOD	WET OR DRY					
NAME:	RSP COPPERS					
						
GRIT:	30	50	100	200	400	800
ATTACH:	velcro back	velcro back	velcro back	velcro back	velcro back	velcro back

CONCRETE POLISHING

TRADITIONAL / PREMIUM

METHOD	DRY				
NAME:	RSP RACE RESINS				
					
GRIT:	200	400	800	1500	3000
ATTACH:	velcro back	velcro back	velcro back	velcro back	velcro back
NAME:	RSP SP3				
GRIT:	100	200	400	800	1500	3000
ATTACH:	velcro back	velcro back	velcro back	velcro back	velcro back	velcro back

METHOD	WET					
NAME:	RSP WET SLICKS					
GRIT:	220	400	600	800	1800	3500
ATTACH:	velcro back	velcro back	velcro back	velcro back	velcro back	velcro back