



# CPS

Concrete Polishing Solutions

# Diamond Tooling Guide



TASK	Mastic and Coating Removal	Rigid Thin-mil Coating Removal Prep for Coating	Aggregate Exposure Surface Restoration	New Construction First Cut Transitional	Polishing Low to Medium Sheen	Polishing Medium to High Sheen	Polishing High Gloss
TOOL	Single/Double PCD Scraper	Black Metal 01 Black Metal 02	Black Metal 03 Black Metal 04 Black Metal 05	Mach 1 Mach 2 Mach 3	Sector 1 Sector 2	Sector 3 Sector 4	Sector 5
Recommended Speed (Propane)	2100 - 2400 RPM	2000 - 2500 RPM	2000 - 2500 RPM	2250 - 2600 RPM	3400 - 3600 RPM	3400 - 3600 RPM	3400 - 3600 RPM
Recommended Speed (Electric)	4 - 6 On Speed Dial	4 - 6 On Speed Dial	4 - 6 On Speed Dial	4 1/2 - 6 1/2 On Speed Dial	10 On Speed Dial	10 On Speed Dial	10 On Speed Dial
Average Production Per Hour	250 - 500 Sq Ft Per Hour	300 - 700 Sq Ft Per Hour	300 - 700 Sq Ft Per Hour	350 - 800 Sq Ft Per Hour	5000 - 6000 Sq Ft Per Hour	5000 - 6000 Sq Ft Per Hour	5000 - 6000 Sq Ft Per Hour

[www.runyonsurfaceprep.com](http://www.runyonsurfaceprep.com)



800.896.8665



Indiana & California Locations